

# Repair Item Report

##	Repair Item	Hierarchical Context	LCN	Part Number	Cost
1	<b>ABS LED</b>	<Top-Level Design>	A0101	GW LED24	5.00
2	<b>BATTERY</b>	<Top-Level Design>	A0102	24V 4YR	60.00
3	<b>BF Level Sensor</b>	<Top-Level Design>	A0103	<Not Assigned>	0.00
4	<b>Brake Fluid</b>	<Top-Level Design>	A0105	<Not Assigned>	0.00
5	<b>Brake Fluid LED</b>	<Top-Level Design>	A0106	GW LED ASSYBL	3.00
6	<b>Brake Light SW</b>	<Top-Level Design>	A0107	<Not Assigned>	45.00
7	<b>Brake Pedal</b>	<Top-Level Design>	A0104	<Not Assigned>	45.00
8	<b>CKV 1 CKV 2 CKV 3 CKV 4</b>	<Top-Level Design>	A0108	CK_V3041	11.00
9	<b>D1</b>	<Top-Level Design>	A0109	<Not Assigned>	3.29
10	<b>DIAG CONN</b>	<Top-Level Design>	A0110	<Not Assigned>	15.00
11	<b>ECU</b>	<Top-Level Design>	A01B01	M468733	227.00
12	<b>F Pump PS R Pump PS</b>	<Top-Level Design>	A0111	<Not Assigned>	23.00
13	<b>FR Line FS Line RR Line RS Line</b>	<Top-Level Design>	A0112	CE150.67359	20.00
14	<b>Front Accumulator Rear Accumulator</b>	<Top-Level Design>	A0113	<Not Assigned>	65.00
15	<b>Front Damper Chamber Rear Damper Chamber</b>	<Top-Level Design>	A0114	A1122024	140.00
16	<b>Front Pump Rear Pump</b>	<Top-Level Design>	A0115	AC25535707	629.00
17	<b>Fuse</b>	<Top-Level Design>	A0116	O321725305	4.00
18	<b>Ignition Switch</b>	<Top-Level Design>	A0117	P711281 kit	87.00
19	<b>L Brake Bulb R Brake Bulb</b>	<Top-Level Design>	A0118	GW LED ASSYBL	3.00
20	<b>LF Tire LR Tire RF Tire RR Tire</b>	<Top-Level Design>	A0119	<Not Assigned>	50.00
21	<b>LF Wheel LR Wheel RF Wheel RR Wheel</b>	<Top-Level Design>	A0120	<Not Assigned>	95.00
22	<b>Master Cylinder</b>	<Top-Level Design>	A0121	CE130.61119	103.00
23	<b>Outlet Valve</b>	LR Disc Assy:	A01B0203	B3246075	45.00
24	<b>Pad2</b>	LR Disc Assy:	A01B0204	P15K1298 kit	147.00
25	<b>Piston 2</b>	LR Disc Assy:	A01B0205	W0133-1819918 R - A118B4613BS F set	210.00
26	<b>Pump Relay Contact</b>	<Top-Level Design>	A0123	<Not Assigned>	15.00
27	<b>Reservoir</b>	<Top-Level Design>	A0124	A1122024	140.00
28	<b>Rotor</b>	LR Disc Assy:	A01B0206	W0133-1819918 R - A118B4613BS F	210.00

				set	
29	<b>RW Brake Bulb</b>	<Top-Level Design>	A0128	GW LED ASSYBL	3.00
30	<b>SENS CONN 1A SENS CONN 2A</b>	<Top-Level Design>	A0125	<Not Assigned>	15.00
31	<b>Solenoid Relay Contacts</b>	<Top-Level Design>	A0127	<Not Assigned>	15.00
32	<b>SS Cable</b>	LR Disc Assy:	A01B0208	MIBRAB11	62.00
33	<b>Tone Ring</b>	LR Disc Assy:	A01B0209	P15K1298 kit	147.00

**Notes:**

Only unique items are listed, based on the attribute **LCN**.

The **Repair Item** column contains all abbreviations assigned to each unique item.

The **Hierarchical Context**, **Part Number** and **Cost** columns contain data from a single instance of each unique item.